FCS Configuration Change Request

ECS Configuration Change Request				Р	age 1 of 3 Pages
CCR No. 98-0380	Logged Dat	te 2/27/98	Rev	Request T	ype CCR
Priority Routine	Urgent	Emergency X	Affected Release	2.0	Change Class II
Title Move RAID Unit EIN#3433 from origin EIN#3432 to t1icg01 EIN#1197					
			Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference None		
RTM Change Start New Baseline					
Problem tlicg01 EIN#1197 does not hav	e enough storage	space and does not h	nave the additional IO	ports to suppo	ort a RAID unit.
Proposed Solution Install SCIP card Serial # AXD581 in t1icg01 EIN#1197. Reallocate SCSI RAID Unit EIN#3433 from origin EIN# 3432 to t1icg01 EIN#1197. NEED: 27 March 1998					
Impact Analysis:					
Organizations Affected:	воо 🗌	Contracts E	CS Chief Eng	FOS	M&O
Procurement	QO 🗌	Rel. Dev	Rel. A	Rel. C	SCDO Arch.
Science Off	Security	Subcontrct	Sys. Eng X	Sys Verf Acpt	
Cost:	None X	Small	Medium	Large	
		(Not exceeding \$100,000)	(\$100,000 to \$500,000)	(Over \$500,000)	
Schedule:	None X	Other			
Additional LOC	al LOC Man-Months				
Materials					
Originator Mark Alabastro		ark Alabastro Signature			3/27/98 Date
Office SED/HWE Office		andy Miller Signature			3/27/98 Date
Disposition Appro	ved X	Approved w/Comm	nent Forv	vard	Disapproved
Comments:					
Commonia.					
CCR C	hairperson Jo	e Guzek			3/30/98
0000	· · · · · · · · · · · · · · · · · · ·	gnature			

CM01OC96 ECS